



# RAILROAD COMMISSION OF TEXAS

## SURFACE MINING AND RECLAMATION DIVISION

March 31, 2009

Mr. Josh Leftwich  
Environmental Manager  
Uranium Energy Corporation (UEC)  
400 Mann Street, Suite 900  
Corpus Christi, Texas 78401

**RE:** Weesatche Project, Goliad County  
Uranium Exploration Permit No. 123B  
**Inspection Report**

Dear Mr. Leftwich:

Enclosed is a copy of the report for the inspection completed on March 25, 2009, at UEC's Weesatche Project, Goliad County.

If you have any questions, please contact me at (512) 305-8813.

Sincerely,

A handwritten signature in blue ink that reads "Mark Schlingen".

Mark Schlingen, Manager  
Inspection and Enforcement

MS/sdj  
Enclosure



# RAILROAD COMMISSION OF TEXAS SURFACE MINING AND RECLAMATION DIVISION URANIUM EXPLORATION INSPECTION REPORT

Project Name: Weesatche Permit Number: 123B  
 Permittee: UEC County: Goliad  
 Industry Representative(s) Present: John Pollock  
 Inspector: Steve Meadows Date of Inspection: March 25, 2009

## I. Field Conditions and Data Collection

Samples Collected: No ☒ Yes ☐ Sample Type: Water ☐ Soil ☐ Vegetation ☐  
 Average Temperature 75 Soil Condition Dry Date Last Rainfall N/A Wind Direction/  
 Velocity (Est.) Calm  
 Photographs Attached: No ☐ Yes ☒ (Complete Section IV)

## II. Enforcement Action Taken

Notice of Violation Issued: No ☒ Yes ☐ NOV No. \_\_\_\_\_  
 Cessation Order Issued: No ☒ Yes ☐ CO No. \_\_\_\_\_



*Steve Meadows*

03/27/2009

Inspector Signature

Date

*Mark Selinger*

Reviewing Supervisor Signature

3-27-2009

Date

The Railroad Commission of Texas complies with Federal and State laws applicable to race, religion, national origin, sex, and disability. Information is available upon request by calling (512) 463-7288 or 1-800-735-2989 if special assistance is required.

Project Name: Weesatche  
Permit Number: 123B  
Inspection Date: March 25, 2009

### III. Comments – Inspection Narrative

- *Document the area of the permit inspected*
- *Discuss observations made during the inspection*
- *Document the results of any field tests taken*
- *Provide a summary of any discussions with industry representatives, along with results, and expectations from those discussions*
- *Describe any enforcement action taken during the inspection, along with facts or evidence supporting the enforcement action*

No drilling activity was underway at the time of this inspection of UEC Permit No. 123. The status of site restorations on the Braquet and Abramite properties was the focus of the inspection as a result. Numerous exploration drilling sites on these areas were examined as seen in photo 1 of borehole CAALT-1, which can be considered typical. Photos 2-4 document the site restoration typical for the cased monitor wells that have recently been completed. The area near cased wells RBLD-3 and RBLD-5, which required the addition of topsoil to complete site restoration in September of 2007, is seen in Photos 5-7. Re-vegetation can be seen to be advancing in spite of the drought conditions. Further observation of site restorations will be the focus of continuing inspections.

**Project Name:** Weesatche  
**Permit Number:** 123B  
**Inspection Date:** March 25, 2009

## VI. Photographs



Photo 1: Site restoration at borehole CAALT-1



Photo 2: Site restoration at monitor wells RBLA-2 and RBLA-5 on the Abramite property.

**Project Name:** Weesatche  
**Permit Number:** 123B  
**Inspection Date:** March 25, 2009

**VI. Photographs**



Photo 3: Monitor wells on Braquet property.



Photo 4: Recent site restoration of monitor well on Braquet property.

**Project Name:** Weesatche  
**Permit Number:** 123B  
**Inspection Date:** March 25, 2009

**VI. Photographs**



Photo 5: Area re-top soiled near wells RBLD-3 and RBLD-5 on 10-3-07.



Photo 6: RBLD-3 and RBLD-3 area on 2-12-08.

<b>Project Name:</b>	<u>Weesatche</u>
<b>Permit Number:</b>	<u>123B</u>
<b>Inspection Date:</b>	<u>March 25, 2009</u>

## VI. Photographs



Photo 7: Monitor wells RBLD-3 and RBLD-5 on 3-25-09.